



# ***REEDSPORT MACHINE & FABRICATION***

**P.O. BOX 508**

**REEDSPORT, OR 97467**

**PHONE: (541) 271-5414      FAX: (541) 271-2614**

**E-MAIL: [rmf@presys.com](mailto:rmf@presys.com)**

**[WWW.reedsportmachine.com](http://WWW.reedsportmachine.com)**

**March 21, 2003**

**To: MKC Berkenbile  
USCG NMLB School**

**Re: 47 MLB Isolator Sleeves and Washers**

**The following is a price quote to accomplish the work listed below:**

**The washers below are stronger and provide more isolation then the ones provided in the kits. The Sleeves are machined correctly to fit a  $\frac{3}{4}$ " hole instead of the ones in the kit which are undersized and the lengths are shortened to the correct thickness of the couplers.**

**8 each- .640"ID X 1.193"OD X .084 Thick Isolator Washer.**

**Total \$8.00 per coupler set**

**8 each- .625 ID X Machined .750 OD X Machined .720 length.  
Teflon/Nomex-lined fiberglass sleeve isolator bushing.**

**Total \$88.00 per coupler set**

**Reedsport Machine & Fabrication appreciates the opportunity to quote on the above work. If you have any further questions, please do not hesitate to call.**

*Rick Stevens, Shop Superintendent*